

Remarketing (List of operations)

Company	ALD Automotive S.A.U.	Claim number	
Custom code		Code	0112874A0
Order date	14/02/2020	Report date	14/10/2019
Expert in charge (Int.)	Marcos Vecino Barreros	Type of intervention	Completion Permit

Vehicle

Make/model	Nissan Qashqai	Finishing / Version	
Motor		Number plate	7344JCJ
Doors		Frame number	SJNFDAJ11U1275609
Kilometers:	185181	Colour:	
Type of vehicle:	Tourism	Vehicle category	1st category
Forms part of			
Workshop		AUTOEXIT	
		Carrer Tarragona, 18-24, RIPOLLET.	
		08291 Ripollet (Barcelona)	
		España	
Implication in the incident			

Impact assessment¹

Detail of damage

Pieces			
Operation	Reference	Tag	Units
Replace	1	Manual de mantenimiento -	1,00
Replace	1	Manual mantenimiento -	1,00
Replace	1	Manual usuario -	1,00
Replace	215/65R1698T-MV	Left rear tyre	1,00
Replace	26560JJ90A	Rear bumper right reflector	1,00
Replace	873204EA5A	Right front bench upholstery	1,00
Replace	873704EA1A	Left front bench upholstery	1,00
Workforce			
Operation	Work	Reference	Tag
Other	Mechanics	GtT9056L	Polish Rear left wing w/ sill panel
Other	Mechanics	GtT7402L	Polish Ext panel left front door
Repair	Bodywork:	GtT92010	Repair Roof
Replace	Decoration	GtT1	Replace Manual de mantenimiento
Replace	Decoration	GtT1	Replace Manual mantenimiento
Replace	Decoration	GtT1	Replace Manual usuario
Replace	Mechanics	PW10A1	Replace Left rear tyre
Replace	Bodywork:	UC22A1	Replace Rear bumper right reflector
Replace	Decoration	VE12A1	Replace Right front bench upholstery
Replace	Decoration	VE26A1	Replace Left front bench upholstery

Legal Text:

"In compliance with the provisions of Art. 335.2 of the L.E.C. /2000 of January 7, the expert who subscribes to the present report, declares under oath to say the truth, that he has performed and will act with the greatest objectivity taking into account both what they may favor and what is susceptible to prejudice either of the parties, and that they know the criminal penalties that could be incurred if they fail to fulfill their duty as an expert. "

Paint			
Operation	Work	Tag	Units
Paint	Paint	Ext panel left rear door Surface	1,00
Paint	Paint	Ext panel left rear door Surface	1,00
Paint	Paint	Front bumper Minor damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Front bumper Minor damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Rear bumper Minor damage Textured Complete 1 colour	1,00
Paint	Paint	Rear bumper Minor damage Textured Complete 1 colour	1,00
Paint	Paint	Roof Mild	1,00
Paint	Paint	Roof Mild	1,00

Legal Text:

"In compliance with the provisions of Art. 335.2 of the L.E.C. /2000 of January 7, the expert who subscribes to the present report, declares under oath to say the truth, that he has performed and will act with the greatest objectivity taking into account both what they may favor and what is susceptible to prejudice either of the parties, and that they know the criminal penalties that could be incurred if they fail to fulfill their duty as an expert. "