



DEKRA Services, S.A.

CIF:A59790923

C/Calabozos nº 12 - 28108 Alcobendas (Madrid)

Tlf:902 36 41 89 Fax:902 10 69 81 Web:www.dekra-expertise.es

Inscrita en el Registro Mercantil de Madrid. Tomo 19787, Libro 0, Sección 8ª, Folio 36, Hoja M 348360, Inscripción 1ª

Remarketing (List of operations)

Company	ALD Automotive S.A.U.	Claim number	
Custom code		Code	0464113A0
Order date	15/09/2021	Report date	06/10/2021
Expert in charge (Int.)	ALVARO GARACHANA MACUA	Type of intervention	Completion Permit

Vehicle

Make/model	Fiat Fiorino	Finishing / Version	
Motor		Number plate	4538JNF
Doors		Frame number	ZFA22500006B14670
Kilometers:	164541	Colour:	
Type of vehicle:		Vehicle category	
Forms part of			
Workshop		OPEL ECHEVARRI TURISMOS C/ IBAIZABAL 73, GALDAKAO. 48960 Galdakao (Bizkaia) España	

Implication in the incident

Impact assessment¹

Detail of damage

Pieces			
Operation	Reference	Tag	Units
Replace	EM69010	Replace Front number plate	1,00
Replace	EM81010	Rear number plate	1,00
Workforce			
Operation	Work	Reference	Tag
Disassemble and assemble	Decoration	7020C30	Remove and refit Rear right door trim
Disassemble and assemble	Bodywork:	7210E10	Remove and refit Front bumper
Other	Decoration	GtT1000	Clean Asiento traseros
Repare	Bodywork:	GtT7101L	Repair Left front wing
Repare	Bodywork:	GtT9070R	Repair Right rear wheel arch
Repare	Bodywork:	GtT8401L	Repair Left rear loading door
Replace	Bodywork:	EM69010	Replace Front number plate
Replace	Bodywork:	EM84910	Replace Rear number plate

Legal Text:

"In compliance with the provisions of Art. 335.2 of the L.E.C. /2000 of January 7, the expert who subscribes to the present report, declares under oath to say the truth, that he has performed and will act with the greatest objectivity taking into account both what they may favor and what is susceptible to prejudice either of the parties, and that they know he criminal penalties that could be incurred if they fail to fulfill their duty as an expert. "

Paint			
Operation	Work	Tag	Units
Paint	Paint	Right front wing Mild	1,00
Paint	Paint	Right front wing Mild	1,00
Paint	Paint	Left front wing Medium	1,00
Paint	Paint	Left front wing Medium	1,00
Paint	Paint	Bonnet Strong	1,00
Paint	Paint	Bonnet Strong	1,00
Paint	Paint	Right bodywork side (rear int section) Mild	1,00
Paint	Paint	Right bodywork side (rear int section) Mild	1,00
Paint	Paint	Left bodywork side (rear int section) Mild	1,00
Paint	Paint	Left bodywork side (rear int section) Mild	1,00
Paint	Paint	Lower panel loading partition Mild	1,00
Paint	Paint	Lower panel loading partition Mild	1,00
Paint	Paint	Loading partition top panel Mild	1,00
Paint	Paint	Loading partition top panel Mild	1,00
Paint	Paint	Front bumper Minor damage Textured Complete 1 colour	1,00
Paint	Paint	Front bumper Minor damage Textured Complete 1 colour	1,00
Paint	Paint	Rear bumper Minor damage Textured Complete 1 colour	1,00
Paint	Paint	Rear bumper Minor damage Textured Complete 1 colour	1,00
Paint	Paint	Right rear wheel arch Medium	1,00
Paint	Paint	Right rear wheel arch Medium	1,00
Paint	Paint	Left rear wheel arch Mild	1,00
Paint	Paint	Left rear wheel arch Mild	1,00
Paint	Paint	Right rear loading door Mild	1,00
Paint	Paint	Right rear loading door Mild	1,00
Paint	Paint	Left rear loading door Mild	1,00
Paint	Paint	Left rear loading door Mild	1,00
Paint	Paint	Right rear door Mild	1,00
Paint	Paint	Right rear door Mild	1,00

Legal Text:

"In compliance with the provisions of Art. 335.2 of the L.E.C. /2000 of January 7, the expert who subscribes to the present report, declares under oath to say the truth, that he has performed and will act with the greatest objectivity taking into account both what they may favor and what is susceptible to prejudice either of the parties, and that they know he criminal penalties that could be incurred if they fail to fulfill their duty as an expert. "