

Remarketing (List of operations)

Company	ALD Automotive S.A.U.	Claim number	
Custom code		Code	0415087A0
Order date	25/05/2021	Report date	25/05/2021
Expert in charge (Int.)	Marcos Vecino Barreros	Type of intervention	Completion Permit

Vehicle

Make/model	Jaguar F-Pace	Finishing / Version	
Motor	2993CC 221KW (300)	Number plate	4220JNZ
Doors		Frame number	SADCA2BK9HA053262
Kilometers:	72120	Colour:	
Type of vehicle:	4x4	Vehicle category	1st category
Forms part of			
Workshop		TRADISA LOGICAUTO DISTRITO RIBERA,37, PRAT DE LLOBREGAT, EL. 08820 Prat de Llobregat, El (Barcelona) España	
Implication in the incident			

Impact assessment¹

Detail of damage

Workforce			
Operation	Work	Reference	Tag
Repair	Bodywork:	GtT4311R	Repair Front right wheel rim
Repair	Bodywork:	GtT4311L	Repair Front left wheel rim
Repair	Bodywork:	GtT7401L	Repair Left front door
Paint			
Operation	Work	Tag	Units
Paint	Paint	Right mirror housing Minor damage Bodywork colour	1,00
Paint	Paint	Right mirror housing Minor damage Bodywork colour	1,00
Paint	Paint	Left mirror housing Minor damage Bodywork colour	1,00
Paint	Paint	Left mirror housing Minor damage Bodywork colour	1,00
Paint	Paint	Tailgate Surface	1,00
Paint	Paint	Tailgate Surface	1,00
Paint	Paint	Left front door Surface	1,00
Paint	Paint	Left front door Surface	1,00
Paint	Paint	Right rear door Surface	1,00
Paint	Paint	Right rear door Surface	1,00
Paint	Paint	Left rear door Surface	1,00
Paint	Paint	Left rear door Surface	1,00

Legal Text:

"In compliance with the provisions of Art. 335.2 of the L.E.C. /2000 of January 7, the expert who subscribes to the present report, declares under oath to say the truth, that he has performed and will act with the greatest objectivity taking into account both what they may favor and what is susceptible to prejudice either of the parties, and that they know he criminal penalties that could be incurred if they fail to fulfill their duty as an expert. "