

Remarketing (List of operations)

Company	ALD Automotive S.A.U.	Claim number	
Custom code		Code	0111073A0
Order date	04/10/2019	Report date	04/10/2019
Expert in charge (Int.)	Joan Fontanals Claramunt	Type of intervention	Completion Permit

Vehicle

Make/model	Alfa Romeo GIULIA	Finishing / Version	
Motor		Number plate	0533JXR
Doors		Frame number	ZAREAEUCU2H7538528
Kilometers:	89136	Colour:	
Type of vehicle:	Tourism	Vehicle category	1st category
Forms part of			
Workshop		AUTOEXIT	
		Carrer Tarragona, 18-24, RIPOLLET.	
		08291 Ripollet (Barcelona)	
		España	
Implication in the incident			

Impact assessment1

Detail of damage

Paint			
Operation	Work	Tag	Units
Paint	Paint	Right mirror housing Minor damage Bodywork colour	1,00
Paint	Paint	Right mirror housing Minor damage Bodywork colour	1,00
Paint	Paint	Front left wheel rim Mild	1,00
Paint	Paint	Front left wheel rim Mild	1,00
Paint	Paint	Right front door ext handle Minor damage Bodywork colour	1,00
Paint	Paint	Right front door ext handle Minor damage Bodywork colour	1,00
Paint	Paint	Front bumper Minor damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Front bumper Minor damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Rear bumper Minor damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Rear bumper Minor damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Right front door Surface	1,00
Paint	Paint	Right front door Surface	1,00
Paint	Paint	Right rear door Surface	1,00
Paint	Paint	Right rear door Surface	1,00

Legal Text:

"In compliance with the provisions of Art. 335.2 of the L.E.C. /2000 of January 7, the expert who subscribes to the present report, declares under oath to say the truth, that he has performed and will act with the greatest objectivity taking into account both what they may favor and what is susceptible to prejudice either of the parties, and that they know he criminal penalties that could be incurred if they fail to fulfill their duty as an expert. "