



DEKRA Services, S.A.

CIF:A59790923

C/Calabozos nº 12 - 28108 Alcobendas (Madrid)

Tlf:902 36 41 89 Fax:902 10 69 81 Web:www.dekra-expertise.es

Inscrita en el Registro Mercantil de Madrid. Tomo 19787, Libro 0, Sección 8ª, Folio 36, Hoja M 348360, Inscripción 1ª

Remarketing (List of operations)

Company	ALD Automotive S.A.U.	Claim number	
Custom code		Code	0459893A0
Order date	02/09/2021	Report date	06/09/2021
Expert in charge (Int.)	Jacinto Del Pino Perez	Type of intervention	Completion Permit

Vehicle

Make/model	Renault Clio	Finishing / Version	
Motor		Number plate	1464KLR
Doors		Frame number	VF15RKJ0A59977485
Kilometers:	87927	Colour:	
Type of vehicle:		Vehicle category	
Forms part of			
Workshop			

MOTOR DOS CANARIAS EUROPCAR
Vial F, Parcela C1 S/N, Vista Hermosa, Urb. Díaz Casanova, PALMAS DE GRAN CANARIA, LAS.
35010 Palmas de Gran Canaria, Las (Palmas, Las)
España

Implication in the incident

Impact assessment¹

Detail of damage

Pieces			
Operation	Reference	Tag	Units
Replace	802852810R	Left front door rear moulding - MATT - New	1,00
Replace		SEGUNDA LLAVE	1,00
Replace	8201345035	Front bumper spoiler	1,00
Replace	8200447464	Right rear wheel hub cap	1,00

Workforce			
Operation	Work	Reference	Tag
Disassemble and assemble	Bodywork:	5213	Remove and refit Front bumper
Repair	Bodywork:	GtT7401L	Repair Left front door
Repair	Bodywork:	GtT7801L	Repair Left rear door
Replace	Bodywork:	5207EM	Replace Left front door rear moulding
Replace	Bodywork:	5362	Replace Front bumper spoiler
Replace	Mechanics	3612	Replace Right rear wheel hub cap

Legal Text:

"In compliance with the provisions of Art. 335.2 of the L.E.C. /2000 of January 7, the expert who subscribes to the present report, declares under oath to say the truth, that he has performed and will act with the greatest objectivity taking into account both what they may favor and what is susceptible to prejudice either of the parties, and that they know he criminal penalties that could be incurred if they fail to fulfill their duty as an expert. "

Paint			
Operation	Work	Tag	Units
Paint	Paint	Left front wing Minor damage Bodywork colour	1,00
Paint	Paint	Left front wing Minor damage Bodywork colour	1,00
Paint	Paint	Right mirror housing Minor damage Textured	1,00
Paint	Paint	Right mirror housing Minor damage Textured	1,00
Paint	Paint	Left mirror housing Minor damage Textured	1,00
Paint	Paint	Left mirror housing Minor damage Textured	1,00
Paint	Paint	Right front door moulding Minor damage Textured	1,00
Paint	Paint	Right front door moulding Minor damage Textured	1,00
Paint	Paint	Right rear door moulding Minor damage Textured	1,00
Paint	Paint	Right rear door moulding Minor damage Textured	1,00
Paint	Paint	Front bumper Minor damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Front bumper Minor damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Rear bumper Moderate damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Rear bumper Moderate damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Left front door Mild	1,00
Paint	Paint	Left front door Mild	1,00

Legal Text:

"In compliance with the provisions of Art. 335.2 of the L.E.C. ./2000 of January 7, the expert who subscribes to the present report, declares under oath to say the truth, that he has performed and will act with the greatest objectivity taking into account both what they may favor and what is susceptible to prejudice either of the parties, and that they know he criminal penalties that could be incurred if they fail to fulfill their duty as an expert. "