

Remarketing (List of operations)

Company	ALD Automotive S.A.U.	Claim number	
Custom code		Code	0110551A0
Order date	02/10/2019	Report date	03/10/2019
Expert in charge (Int.)	Hector Manzanera Lopez	Type of intervention	Completion Permit

Vehicle

Make/model	Jaguar E-Pace	Finishing / Version	
Motor		Number plate	2040KNF
Doors		Frame number	SADCA2BN0JA254323
Kilometers:	15279	Colour:	
Type of vehicle:	Tourism	Vehicle category	1st category
Forms part of			
Workshop		AUTOEXIT	
		Carrer Tarragona, 18-24, RIPOLLET.	
		08291 Ripollet (Barcelona)	
		España	

Implication in the incident

Impact assessment¹

Detail of damage

Pieces			
Operation	Reference	Tag	Units
Replace	1	SEGUNDA LLAVE -	1,00
Workforce			
Operation	Work	Reference	Tag
Replace	Decoration	Gt1	Replace SEGUNDA LLAVE
Paint			
Operation	Work	Tag	Units
Paint	Paint	Right mirror housing Minor damage Bodywork colour	1,00
Paint	Paint	Right mirror housing Minor damage Bodywork colour	1,00
Paint	Paint	Front bumper Minor damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Front bumper Minor damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Rear bumper Minor damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Rear bumper Minor damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Tailgate Surface	1,00
Paint	Paint	Tailgate Surface	1,00
Paint	Paint	Left rear door Surface	1,00
Paint	Paint	Left rear door Surface	1,00

Legal Text:

"In compliance with the provisions of Art. 335.2 of the L.E.C. /2000 of January 7, the expert who subscribes to the present report, declares under oath to say the truth, that he has performed and will act with the greatest objectivity taking into account both what they may favor and what is susceptible to prejudice either of the parties, and that they know the criminal penalties that could be incurred if they fail to fulfill their duty as an expert. "