



DEKRA Services, S.A.

CIF:A59790923

C/Calabozos nº 12 - 28108 Alcobendas (Madrid)

Tlf:902 36 41 89 Fax:902 10 69 81 Web:www.dekra-expertise.es

Inscrita en el Registro Mercantil de Madrid. Tomo 19787, Libro 0, Sección 8ª, Folio 36, Hoja M 348360, Inscripción 1ª

## Remarketing (List of operations)

Company	ALD Automotive S.A.U.	Claim number	
Custom code		Code	0087951A0
Order date	07/06/2019	Report date	07/06/2019
Expert in charge (Int.)	Jordi Pérez López	Type of intervention	Completion Permit

### Vehicle

Make/model	Ford Kuga	Finishing / Version	
Motor		Number plate	0406KJZ
Doors		Frame number	WF0AXXWPMAY15896
Kilometers:	22668	Colour:	
Type of vehicle:		Vehicle category	
Forms part of			
Workshop		AUTOEXIT	
		Carrer Tarragona, 18-24, RIPOLLET.	
		08291 Ripollet (Barcelona)	
		España	
Implication in the incident			

### Impact assessment<sup>1</sup>

#### Detail of damage

Pieces			
Operation	Reference	Tag	Units
Replace	00002	CENICERO -	1,00
Replace	1	SEGUNDA LLAVE -	1,00
Workforce			
Operation	Work	Reference	Tag
Repair	Bodywork:	GtT85010	Repair Windscreen glass
Repair	Bodywork:	GtT7801R	Repair Right rear door
Disassemble and assemble	Mechanics	GtT00002	Replace CENICERO
Disassemble and assemble	Decoration	GtT1	Replace SEGUNDA LLAVE

#### Legal Text:

"In compliance with the provisions of Art. 335.2 of the L.E.C. /2000 of January 7, the expert who subscribes to the present report, declares under oath to say the truth, that he has performed and will act with the greatest objectivity taking into account both what they may favor and what is susceptible to prejudice either of the parties, and that they know he criminal penalties that could be incurred if they fail to fulfill their duty as an expert. "

Paint			
Operation	Work	Tag	Units
Paint	Paint	Right front door ext handle Minor damage Bodywork colour	1,00
Paint	Paint	Right front door ext handle Minor damage Bodywork colour	1,00
Paint	Paint	Front bumper Minor damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Front bumper Minor damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Rear bumper (right area) Minor damage Bodywork colour	1,00
Paint	Paint	Rear bumper (right area) Minor damage Bodywork colour	1,00
Paint	Paint	Rear bumper Minor damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Rear bumper Minor damage Bodywork colour Complete 1 colour	1,00
Paint	Paint	Right front door Surface	1,00
Paint	Paint	Right front door Surface	1,00
Paint	Paint	Left front door Surface	1,00
Paint	Paint	Left front door Surface	1,00
Paint	Paint	Right rear door Surface	1,00
Paint	Paint	Right rear door Surface	1,00
Paint	Paint	Rear bumper spoiler Minor damage Bodywork colour	1,00

#### Legal Text:

"In compliance with the provisions of Art. 335.2 of the L.E.C. /2000 of January 7, the expert who subscribes to the present report, declares under oath to say the truth, that he has performed and will act with the greatest objectivity taking into account both what they may favor and what is susceptible to prejudice either of the parties, and that they know he criminal penalties that could be incurred if they fail to fulfill their duty as an expert. "